

Laura S. Olton General Counsel Ocean State Division

April 13, 2006

VIA HAND DELIVERY & ELECTRONIC MAIL

Luly E. Massaro, Commission Clerk Rhode Island Public Utilities Commission 89 Jefferson Boulevard Warwick, RI 02888

> RE: Docket 3628 – The Narragansett Electric Company's Service Quality Plan Feeder Ranking Report – 1st Quarter 2006

Dear Ms. Massaro:

Enclosed please find ten (10) copies of the Feeder Ranking Report for the first quarter of 2006, filed in accordance with the Additional Reporting Criteria, Item 1, of The Narragansett Electric Company, d/b/a National Grid, Service Quality Plan effective January 1, 2005.

Thank you for your attention to this filing. Please feel free to contact me if you have any questions at (401) 784-7667.

Very truly yours,

Laura S. Olton

Laura S. Olton

Enclosures

Docket 3628 Service List cc:

Paul Roberti, Esq.

Steve Scialabba, Division

nationalgrid Ocean State Division Feeder Rankings 4th Quarter:October 2005- December 2005

Feeder Ranking By Quarter Naragansett Electric Jan 2006 - Mar 2006

			Jan 2006 - Mar 2006						
Rank	Feeder	Freq.	Cities/Towns Served	No. of Customers	No of Events	Average Duration	Total Customer Mins.	Causes	Corrective Actions
1	105K1	6	LINCOLN	8	6	417.00	3336	Feeder Lockout - Vehicle Pole Accident	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
								Feeder Lockout - Substation Equipment Related	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
								Feeder Lockout - Vehicle Pole Accident	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
								Feeder Lockout - Unknown Cause	Feeder was patrolled and no cause was found
								Feeder Lockout - Unknown Cause	Feeder was patrolled and no cause was found
								Feeder Lockout - Company Construction	Conductors were Repaired and Circuit Was Restored to Normal Operation
2	20F2	3.01	EAST PROVIDENCE	1959	5	216.86	424833	Primary Wire Down - Tree Condition	Removed Tree from Primaries and the Circuit Was Restored to Normal Operation
								Feeder Lockout - Deteriorated Equipment	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
								Fuse Link Failure - Flying Debris	Transformer Fuse Replaced
								Substation Equipment Lockout - Animal	Equipment Was Tested and Circuit Was Restored to Normal Operation
								Planned Outage - Equipment Maintenance	Equipment Was Restored to Normal Operation Following Planned Work
3	102W54	3.00	CUMBERLAND	2180	6	246.47	537304	Substation Equipment Failure	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
								Feeder Lockout - Tree Related	Removed Tree from Primaries and the Circuit Was Restored to Normal Operation
								Feeder Lockout - Tree Related	Removed Tree from Primaries and the Circuit Was Restored to Normal Operation
								Feeder Lockout - Tree Related	Removed Tree from Primaries and the Circuit Was Restored to Normal Operation
								Fuse Link Failure - Weather	Transformer Fuse Replaced
								Fuse Link Failure - Deterioration	Replaced and re-fused deteriorated cutout.
4	102W51	2.04	CENTRAL FALLS	3385	4	159.23	538978	Substation Equipment Failure	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
			LINCOLN					Fuse Link Failure - Weather	Transformer Fuse Reset
			PAWTUCKET					Pole Top Recloser Lockout - Tree Limb	Removed Tree Limb from Primaries and Restored Circuit to Normal
			CUMBERLAND					Fuse Link Failure - Unknown Cause	Circuit was Patrolled - No Cause Found - Refused Line Cutout
5	102K22	2.00	CUMBERLAND	9	2	178.00	1602	Substation Equipment Failure	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
								Feeder Lockout - Loss of Supply - Tree Condition	Removed Tree from Primaries of Supply Circuit and the Circuit Was Restored to Normal Operation
6	49J1	2.00	WEST WARWICK	619	2	207.10	128196	Feeder Lockout - Vehicle Pole Accident	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
			COVENTRY					Feeder Lockout - Company Construction	Conductors were Repaired and Circuit Was Restored to Normal Operation
7	45F2	1.55	GLOUCESTER	1164	8	132.21	153896	Fuse Link Failure - Tree Condition	Line Fuse Replaced
			SCITUATE					Feeder Lockout - Tree Related	Removed Tree from Primaries and the Circuit Was Restored to Normal Operation
			SMITHFIELD					Fuse Link Failure - Tree Condition	Line Fuse Replaced
								Fuse Link Failure - Tree Condition Fuse Link Failure - Weather	Line Fuse Replaced Transformer Fuse Replaced
								Fuse Link Failure - Weather	Line Fuse Replaced
								Planned Outage - Equipment Maintenance	Equipment Was Restored to Normal Operation Following Planned Work
								Fuse Link Failure - Tree Condition	Transformer Fuse Replaced
8	27F1	1.48	WARWICK	2283	4	81.85	186867	Fuse Link Failure - Tree Condition	Line Fuses Replaced
	2		CRANSTON	2200	·	01.00	100001	Feeder Lockout - Equipment Failure	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
								Fuse Link Failure - Animal	Transformer Fuse Replaced
								Pole Top Recloser Lockout - Equipment Failure	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
9	61F1	1.42	EAST GREENWICH	273	2	117.25	32008	Feeder Lockout - Loss of Supply - Tree Condition	Removed Tree from Primaries of Supply Circuit and the Circuit Was Restored to Normal Operation
				1			ĺ	Fuse Link Failure - Tree Condition	Line Fuse Replaced
									Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
10	54F1	1.39	COVENTRY SCITUATE	3020	26	194.81	588331	Feeder Lockout - Vehicle Pole Accident Fuse Link Failure - Tree Condition	Line Fuses Replaced
			22	1			I	Fuse Link Failure - Tree Condition	Line Fuse Replaced
				1			ĺ	Fuse Link Failure - Tree Condition	Line Fuses Replaced
				1			I	Fuse Link Failure - Tree Condition	Line Fuse Replaced
				1			I	Fuse Link Failure - Tree Condition	Line Fuse Replaced
							ĺ	Fuse Link Failure - Equipment Failure	Repaired Damaged Equipment and Transformer Fuse Replaced
							ĺ	Fuse Link Failure - Equipment Failure	Repaired Damaged Equipment and Transformer Fuse Replaced
							ĺ	Fuse Link Failure - Tree Condition	Line Fuse Replaced
				1			l	Fuse Link Failure - Tree Condition	Line Fuses Replaced
				1			I	Pole Top Recloser Lockout - Tree Condition	Removed Tree from Primaries and Restored Circuit to Normal
ı I		1 I		1			I	Fuse Link Failure - Tree Condition	Line Fuse Replaced

national**grid** Ocean State Division Feeder Rankings 4th Quarter:October 2005- December 2005

							Total	T	
				No. of	No of	Average	Customer		
Rank	Feeder	Freq.	Cities/Towns Served	Customers	Events	Duration	Mins.	Causes	Corrective Actions
								Fuse Link Failure - Tree Condition	Line Fuses Replaced
								Fuse Link Failure - Tree Condition	Line Fuse Replaced
								Fuse Link Failure - Tree Condition	Transformer Fuse Replaced
								Fuse Link Failure - Tree Condition	Line Fuse Replaced
								Fuse Link Failure - Tree Condition	Transformer Fuse Replaced
								Fuse Link Failure - Tree Condition	Transformer Fuse Replaced
								Fuse Link Failure - Animal	Transformer Fuse Replaced
								Fuse Link Failure - Equipment Failure	Repaired Damaged Equipment and Line Fuse Replaced
								Fuse Link Failure - Tree Condition	Line Fuse Replaced
								Fuse Link Failure - Equipment Failure	Repaired Damaged Equipment and Transformer Fuse Replaced
								Fuse Link Failure - Unknown Cause	Circuit was Patrolled - No Cause Found - Refused Line Cutout
								Fuse Link Failure - Tree Condition	Line Fuse Replaced
								Fuse Link Failure - Equipment Failure	Repaired Damaged Equipment and Transformer Fuse Replaced
								Fuse Link Failure - Tree Condition	Line Fuse Replaced
11	102W44	1.37	LINCOLN	1678	2	101.42	170191	Substation Equipment Failure	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
			CUMBERLAND					Pole Top Recloser Lockout - Tree Condition	Removed Tree from Primaries and Restored Circuit to Normal
12	102W52	1.32	CENTRAL FALLS	678	2	87.93	59619	Substation Equipment Failure	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
			CUMBERLAND					Planned Switching - Improper Contact	Closed switch and checked for proper seating.
13	127W42	1.25	NORTH SMITHFIELD	518	2	50.33	26072	Feeder Lockout - Tree Related	Removed Tree from Primaries and the Circuit Was Restored to Normal Operation
								Planned Switching - Improper Contact	Closed switch and checked for proper seating.
14	34F2	1.23	GLOCESTER	2312	18	87.73	202841	Feeder Lockout - Tree Related	Removed Tree from Primaries and the Circuit Was Restored to Normal Operation
			FOSTER					Fuse Link Failure - Tree Condition	Line Fuse Replaced
			SCITUATE					Fuse Link Failure - Tree Condition	Line Fuses Replaced
								Fuse Link Failure - Tree Condition	Line Fuse Replaced
								Fuse Link Failure - Tree Condition	Transformer Fuse Replaced
								Fuse Link Failure - Tree Condition	Transformer Fuse Replaced
								Fuse Link Failure - Tree Condition	Line Fuse Replaced
								Fuse Link Failure - Equipment Failure Fuse Link Failure - Equipment Damage	Repaired Damaged Equipment and Line Fuse Replaced
								Fuse Link Failure - Equipment Damage Fuse Link Failure - Tree Condition	Repaired Damaged Equipment and Line Fuse Replaced Transformer Fuse Replaced
								Fuse Link Failure - Weather	Line Fuse Replaced
								Fuse Link Failure - Weather	Transformer Fuse Replaced
								Fuse Link Failure - Weather	Line Fuse Replaced
								Fuse Link Failure - Weather	Transformer Fuse Replaced
		l I						Fuse Link Failure - Tree Condition	Line Fuse Replaced
								Fuse Link Failure - Deterioration	Line Fuse Replaced
								Fuse Link Failure - Unknown Cause	Circuit was Patrolled - No Cause Found - Refused Line Cutout
								Fuse Link Failure - Deterioration	Transformer Fuse Replaced
15	154J4	1.20	NEWPORT	76	2	309.58	23528	Feeder Lockout - Cable Insulation Failure	Repaired Cable and Restored Circuit to Normal Operation
								Feeder Lockout - Cable Insulation Failure	Repaired Cable and Restored Circuit to Normal Operation
16	51J12	1.08	NEWPORT	228	1	49.83	11362	Pole Top Recloser Lockout - Cable Insulation Failure	Repaired Cable and Restored Circuit to Normal Operation
17	30J3	1.08	PAWTUCKET	842	6	102.15	86007	Substation Equipment Failure	Damaged Equipment Was Repaired and Circuit Was Restored to Normal Operation
								Planned Outage - Equipment Maintenance	Equipment Was Restored to Normal Operation Following Planned Work
								Planned Outage - Equipment Maintenance	Equipment Was Restored to Normal Operation Following Planned Work
		l I						Planned Outage - Equipment Maintenance	Equipment Was Restored to Normal Operation Following Planned Work
								Planned Outage - Equipment Maintenance	Equipment Was Restored to Normal Operation Following Planned Work
								Planned Outage - Equipment Maintenance	Equipment Was Restored to Normal Operation Following Planned Work
18	50J3	1.04	NORTH PROVIDENCE	1013	3	28.20	28568	Feeder Lockout - Company Construction	Conductors were Repaired and Circuit Was Restored to Normal Operation
								Fuse Link Failure - Weather	Line Fuse Replaced
								Planned Outage - Equipment Maintenance	Equipment Was Restored to Normal Operation Following Planned Work

The Total No. Of Customers Served Will Vary Throughout The Year Due to New Activations, Terminations Of Service Or Rearrangements of the Company's Distribution System FREQUENCY=(Total No. Of Cust's Interrupted) / (Total No. Of Cust's Served By Feeder)

TOTAL CUSTOMER MINUTES (CMI)=Sum Of [((Number Of Customers Interrupted) X (Duration Of Interruption)) For Each Event)

Certificate of Service

I hereby certify that a copy of the cover letter and / or any materials accompanying this certificate has been mailed or hand-delivered to the parties listed below.

Joanne M. Scanlon

April 13, 2006
Date

Narragansett Electric Company – Service Quality Plan Docket 3628 - Service List

Name	E-mail Distribution List	Phone/FAX
Laura Olton, Esq. National Grid	Laura.olton@us.ngrid.com	401-784-7667 401-784-4321
280 Melrose Street Providence RI 02907-1438	Joanne.scanlon@us.ngrid.com	
Leo Wold, Esq. Dept. of Attorney General 150 South Main St. Providence RI 02903	Proberti@riag.state.ri.us Steve.scialabba@ripuc.state.ri.us David.stearns@ripuc.state.ri.us Al.contente@ripuc.state.ri.us	401-222-2424 ext. 2299 - 401-222-3016
John Stutz Tellus Institute 11 Arlington St. Boston MA 02116-3411	Jstutz@tellus.org	
W. Mark Russo, Esq.	mrusso@frlawri.com	
Original & nine (9) copies file w/: Luly E. Massaro, Commission Clerk Public Utilities Commission 89 Jefferson Boulevard Warwick RI 02888	Lmassaro@puc.state.ri.us Sfrias@puc.state.ri.us Tmassaro@puc.state.ri.us	401-941-4500
W. Mark Russo, Esq.	mrusso@frlawri.com	

cc: Steve Scialabba, RI Division